

HISTORIC AMERICAN BUILDINGS SURVEY  
INDEX TO PHOTOGRAPHS

HABS  
ME,  
15-COLUF,  
1-

Addendum to  
Judge Thomas Ruggles House  
North side of principal road (former U.S. Route 1)  
0.1 miles SW of Pleasant River Bridge, facing  
intersection of unnumbered road to Addison  
Columbia Falls  
Washington County  
Maine

HABS No. ME-26

Cortlandt V. D. Hubbard, Photographer      October, 1973

- ME-26-9      SOUTH FRONT FROM THE SOUTHWEST
- ME-26-10      SOUTH FRONT FROM THE SOUTHWEST (TAKEN AT DIFFERENT TIME)
- ME-26-11      SOUTH FRONT FROM THE SOUTHEAST
- ME-26-12      INTERIOR, HALL AND STAIRCASE, LOOKING SOUTH, SHOWING PALLADIAN WINDOW
- ME-26-13      INTERIOR, HALL AND STAIRCASE, LOOKING SOUTH, SHOWING PALLADIAN WINDOW  
(CLOSER, MORE OBLIQUE VIEW)
- ME-26-14      INTERIOR, HALL AND STAIRCASE, LOOKING NORTH
- ME-26-15      INTERIOR, DINING (EAST) ROOM, LOOKING NORTHEAST, SHOWING FIREPLACE
- ME-26-16      INTERIOR, PARLOR (WEST ROOM), LOOKING NORTHWEST, SHOWING FIREPLACE

HISTORIC AMERICAN BUILDINGS SURVEY  
INDEX TO PHOTOGRAPHS

HABS  
ME,  
15-COLOR,  
1-

ADDENDUM TO  
JUDGE THOMAS RUGGLES HOUSE  
Pleasant River Bridge Vicinity  
Columbia Falls  
Washington County  
Maine

HABS No. ME-26

ME-26-1 through ME-26-15 were transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Cortlandt V. D. Hubbard, Photographer, October 1973

ME-26-16 (CT)          SOUTH FRONT FROM THE SOUTHEAST